

Figure 1. Fresno Sears, TXB-S422 First try

Trace	Use
1	Command from RC58 controller.
2	Response from Spectra with TXB-S422 installed.

¹\$Header: d:/txb-s422/RCS/pictsf2.tex,v 1.10 2001-05-22 08:28:18-07 Hamilton Exp Hamilton \$

²\$Header: d:/txb-s422/RCS/pictsf2.inc,v 1.2 2001-11-30 15:12:03-08 Hamilton Exp Hamilton \$




Figure 2. Fresno Sears, TXB-S422 Duration of the return to quiescent.

Trace	Use
1	Command from RC58 controller.
2	Response from Spectra with TXB-S422 installed.




Figure 3. Fresno Sears, TXB-S422 Reply to a command.

Trace	Use
1	Command from RC58 controller.
2	Response from Spectra with TXB-S422 installed.




Figure 4. Fresno Sears, TXB-S422 Time from start of a command to its reply.

Trace	Use
1	Command from RC58 controller.
2	Response from Spectra with TXB-S422 installed.




Figure 5. Fresno Sears, TXB-S422 Time between retransmitted commands.

Trace	Use
1	Command from RC58 controller.
2	Response from Spectra with TXB-S422 installed.




Figure 6. Fresno Sears, TXB-S422 Second time between retransmitted commands.

Trace	Use
1	Command from RC58 controller.
2	Response from Spectra with TXB-S422 installed.




Figure 7. Fresno Sears, TXB-S422 Responses to “queries”.

Trace	Use
1	Command from RC58 controller.
2	Response from Spectra with TXB-S422 installed.




Figure 8: Fresno Sears, TXB-S422 Power up sequence. Note that the controller's response is missing.

Trace	Use
1	Command from RC58 controller.
2	Response from Spectra with TXB-S422 installed.